ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0255, W0247, W0245, W0261, W0025

Street Name
Mahadevapura Village Rd, 4th Crs, NA

Significant Landmark
somanna matta road

Segment No.
10/C-W0255/S121104

Total Length (m)
173.31

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	52.12	77.556351	13.069245	77.556228	13.068789	RI-A22	W0014
2	42.85	77.557390	13.062764	77.557387	13.062376	W0247	SDW
3	78.34	77.557250	13.062336	77.557972	13.062361	W0164	W0261

Work Details

History of Road / Lane / Circles

Name of the Work
Ward no 10 (Doddabommasandra)

Sanctioned Estimated Amount (Rs.)
1500000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Ward no 10 (Doddabommasandra) Improvement to roads and drains of somanna matta road in chamundeswari layout in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-16-000013

Work Order No.
EE/BTP/BBMP/E-PMT/304/2015-16

Work Order Date
23/03/2016

Period of Extention
90 DAYS

Defect Liability Period From
23/03/2016

Defect Liability Period To
22/03/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
N.M SHIVAKUMAR

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

9448956136

Field Inspection Details

Number of Trees	Any Other Information	Name
4		MADHAVA RAO
Date of Inspection	**Remarks**	
21/08/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0255, W0247, W0245, W0261,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	21/08/2016	20/09/2016	COMPLETED
SE	VASU K M	21/08/2016	20/09/2016	COMPLETED
EE	YARAPPA REDDY	21/08/2016	20/09/2016	COMPLETED
AEE	SHIVAKUMAR	21/08/2016	20/09/2016	COMPLETED
AE	MADHAVA RAO	21/08/2016	20/09/2016	COMPLETED
AE	MADHAVA RAO	21/08/2016	20/09/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0255, W0247, W0245, W0261,